


# Addendum

During installation, position this updated alignment and calibration tool (part numbers 840-3276 and 840-3277) so that the connecting cable extends toward to microscope, as shown.

If the tool is installed in any other orientation, installation tests will fail.



Position the tool so that the cable extends toward the microscope